





Test report on a shot peened cast iron crankshaft



	= cast
	= nitrided
	= shot peened





Other materials and alloys


The shot peening process also induces compressive residual stress in stainless steels, aluminium alloys, titanium alloys, nickel based alloys, powdered metals, cast irons, cast steels, etc., with the same resultant improvement of fatigue life. Crack growth and crack propagation is in the same way hindered.




Test report on a shot peened cast iron rocker arm



Rocker arm



26 Ni Cr Mo V 145



GK-Al Si Mg-Wa